

## STUCCO PERFORMANCE



**YEAR COMPLETED:  
2001-2008**  
**SQUARE FOOTAGE:  
ABOUT 2 MILLION**

*Residential Development*

Master Wall® acrylic modified OCS was specified for these projects. Several years after installation it was noted that the stucco was bulging, bending and eventually cracking over the garage doors. Master Wall investigated the condition in cooperation with the builder and applicator.

Test cuts were taken of the exterior and the interior was examined. We determined the cause of the failure was unsupported gable trusses. The builder took immediate action to support the gable trusses and repaired them with new Master Wall materials.

